



Environmental Support Network, Inc.

5376 Fulton Drive, NW – Canton, Ohio 44718 – (330) 494-0905
www.environmental-support.com

November 14, 2012

Mr. Jay Dahl
Project Manager
BJAAM Environmental, Inc.
P.O. Box 523
472 Elm Ridge Avenue
Canal Fulton, Ohio 44614
(330) 854-5300

RE: The Former Stewart Brothers Paint
Main Building
Alliance, Ohio

Dear Jay,

The following includes the results from the asbestos sampling that you requested.

On November 5, 2012, Environmental Support Network, Inc. acquired samples of construction materials from the former Stewart Brothers Paint Property's Main Building located at 1010 North Union Avenue in Alliance, Ohio 44601. The samples were taken of the construction materials resident in the building. Random sampling was conducted pursuant to 40 CFR 763.86. The construction materials sampled are those materials that might become friable during the forces of a mechanical demolition activity. The purpose of conducting this sampling was to acquire pre-demolition samples of construction materials to satisfy the National Emission Standard for Hazardous Air Pollutants (NESHAP's) regulations as codified in 40 CFR Part 61.

During this inspection, twenty-six-(26) samples were taken. Two-(2) of the samples were multi-layered thus bringing the total sample count to twenty-eight-(28). Each layer was tested discretely. The samples were ceiling plaster (CP), wall plaster (WP), ceiling tile (CT), drywall walls, and the roof membrane which may become disturbed and friable during the course of the demolition activities. The following chart presents a description of the materials sampled and the associated analytical results.

#	LOCATION	AREA	TYPE	COLOR	TEXTURE	RESULT
01	Main -1F	Mill Rm-N	CP	White	Hard,Rough	Trace
02	Main -1F	Mill Rm-S	CP	White	Hard,Rough	Trace
03	Main -1F	Mill Rm-W	CP	White	Hard,Rough	Trace
04	Main -2F	Processing-E	CP	White	Hard,Rough	Trace
05	Main-2F	Procesing-W	CP	Green	Hard,Rough	Trace
06	Main-2F	E.Offices-N	CP	Pink	Hard,Rough	Trace
07	Main-2F	E.Stairs-C	CP	White	Hard,Rough	Trace

08	Main-2F	Restroom-C	WP	Orange	Hard,Rough	Trace
09	Main-2F	Processing-N	WP	White	Hard,Rough	Trace
10	Main-1F	E.Stairs-C	WP	Pink	Hard,Rough	Trace
11	Main-2F	E.Stairs-C	WP	Pink	Hard,Rough	Trace
12	Main-2F	OfficeHall-N	WP	White	Hard,Rough	Trace
13A	Main-1F	Lab-S	Fume hood	Brown	Soft,Smooth	NAD
13B	Main-1F	Lab-S	Mastic	Tan	Hard, tarry	NAD
14A	Main-1F	Lab-N	Fume hood	Brown	Soft,Smooth	NAD
14B	Main-1F	Lab-N	Mastic	Tan	Hard, tarry	NAD
15	Main-1F	Lab-N	CT	White	Soft,Fissured	NAD
16	Main-2F	Office-E	CT	White	Soft,Fissured	NAD
17	Main-2F	Restroom-C	CT	White	Soft,Fissured	NAD
18	Main-2F	Hall-C	CT	White	Soft,Fissured	NAD
19	Main-2F	Landing-C	CT	White	Soft,Fissured	NAD
20	Main	Roof-E	Membrane	Black	Hard,Smooth	NAD
21	Main	Roof-W	Membrane	Black	Hard,Smooth	NAD
22	Main	Roof-N	Membrane	Black	Hard,Smooth	NAD
23	Main-1F	ShipOff-E	CT	White	Soft,Smooth	NAD
24	Main-1F	ShipOff-W	CT	White	Soft,Smooth	NAD
25	Main-1F	Lab-E	Drywall	White	Hard,Smooth	NAD
26	Main-1F	Lab-W	Drywall	White	Hard,Smooth	NAD

The aforementioned samples were analyzed utilizing Polarized Light Microscopy (PLM). Sample analysis was conducted pursuant to EPA Method 600/R-93/116. The samples were submitted to an independent testing laboratory known as Environmental Hazards Services in Richmond, Virginia. Environmental Hazards Services is a participant in the National Voluntary Laboratory Accreditation Program (NVLAP).

As can be seen from the above, most of the samples were negative for asbestos content. The NAD designation means, "no asbestos detected" in the sample submitted. These materials need not be removed prior to demolition. The acronym ACM designates, "asbestos-containing materials." Any sample demonstrating an asbestos content in excess of 1% is considered to be a regulated asbestos containing material (ACM).

Some materials tested have between a trace and 1% asbestos content which is very close to the EPA's 1% Action Limit by the PLM methodology. According to NESHAP's, the EPA requires that these materials be determined to be less than one percent using alternate methodologies. This methodology is the Point-Count Method. The Point-Count Methodology is more specific than the Bulk PLM Methodology. The following includes the results of the Point-Count testing.

#	LOCATION	AREA	TYPE	COLOR	TEXTURE	P-C RESULT
01	Main -1F	Mill Rm-N	CP	White	Hard,Rough	<0.25% ACM
02	Main -1F	Mill Rm-S	CP	White	Hard,Rough	<0.25% ACM
03	Main -1F	Mill Rm-W	CP	White	Hard,Rough	0.25% ACM
04	Main -2F	Processing-E	CP	White	Hard,Rough	<0.25% ACM
05	Main-2F	Procesing-W	CP	Green	Hard,Rough	<0.25% ACM
06	Main-2F	E.Offices-N	CP	Pink	Hard,Rough	0.25% ACM
07	Main-2F	E.Stairs-C	CP	White	Hard,Rough	1.25% ACM

08	Main-2F	Restroom-C	WP	Orange	Hard,Rough	0.25% ACM
09	Main-2F	Processing-N	WP	White	Hard,Rough	<0.25% ACM
10	Main-1F	E.Stairs-C	WP	Pink	Hard,Rough	<0.25% ACM
11	Main-2F	E.Stairs-C	WP	Pink	Hard,Rough	0.25% ACM
12	Main-2F	OfficeHall-N	WP	White	Hard,Rough	<0.25% ACM

Based on the above and pursuant to the EPA's Representative Sampling Protocol, the ceiling plaster in the Main Building is considered to be a regulated asbestos containing material. This is because one or more of the samples from the homogeneous area (ceiling plaster) exceeded the 1% ACM concentration as specified by NESHAP's. Therefore, the ceiling plaster in the Main Building is considered a regulated asbestos containing material.

Please note, the basement level of the building is excluded from this assessment. At the time of this assessment, there was approximately two feet of standing water across that level of the building. For safety and sanitary reasons, the basement level was not entered.


A search was conducted specifically for thermal system insulation (TSI) in the building. All TSI in walls and ceilings were either, a) not present, or b) plainly marked fiberglass, mineral wool, or foam which are not suspected to contain asbestos. No potentially asbestos containing materials were found except the materials documented above.

An inspection was also conducted for possible non-friable ACM resident in the building. Non-friable materials such as floor tile, mastic, etc. were not found to be present. No other suspect materials were found beyond those sampled above.

Based on the above, the ceiling plaster materials in the Main Building are regulated asbestos containing materials. At the current time, these materials are mostly in good condition. However, these materials will become friable by the forces of a mechanical demolition activity. Therefore, these materials should be removed prior to demolition by an asbestos abatement contractor licensed in the State of Ohio. There is approximately 4,100 square feet of the ceiling plaster materials present on the main and upper level of the building. If the same material is present in the basement, this value may increase. Attached is a sketch showing the areas where the ACM is present.

Finally, Jay, if you have any questions regarding the above please contact me at (330) 494-0905. As always, thank you.

Sincerely,



William P. Racine
Environmental Consultant
CAHES #31746

ATTACHMENT A

BULK ASBESTOS SAMPLING BY PLM



Environmental Support Network, Inc.

5376 Fulton Drive, NW – Canton, Ohio 44718 – (330) 494-0905

CHAIN OF CUSTODY

Rush

CLIENT: ENVIRONMENTAL SUPPORT NETWORK, INC.
5376 FULTON DRIVE, NW
CANTON, OHIO 44718
PHONE: (330) 494-0905

FAX: (330) 494-1650

SITE: BJAAM-SB-Main
Alliance, OH


ANALYSIS: POLARIZED LIGHT MICROSCOPY
BULK ASBESTOS ANALYSIS

#	LOCATION	AREA	TYPE	COLOR	TEXTURE	TEST
01	Main -1F	Mill Rm-N	CP	White	Hard,Rough	PLM
02	Main -1F	Mill Rm-S	CP	White	Hard,Rough	PLM
03	Main -1F	Mill Rm-W	CP	White	Hard,Rough	PLM
04	Main -2F	Processing-E	CP	White	Hard,Rough	PLM
05	Main-2F	Processing-W	CP	Green	Hard,Rough	PLM
06	Main-2F	E.Offices-N	CP	Pink	Hard,Rough	PLM
07	Main-2F	E.Stairs-C	CP	White	Hard,Rough	PLM
08	Main-2F	Restroom-C	WP	Orange	Hard,Rough	PLM
09	Main-2F	Processing-N	WP	White	Hard,Rough	PLM
10	Main-1F	E.Stairs-C	WP	Pink	Hard,Rough	PLM
11	Main-2F	E.Stairs-C	WP	Pink	Hard,Rough	PLM
12	Main-2F	OfficeHall-N	WP	White	Hard,Rough	PLM
13	Main-1F	Lab-S	Fume hood	Brown	Soft,Smooth	PLM
14	Main-1F	Lab-N	Fume hood	Brown	Soft,Smooth	PLM
15	Main-1F	Lab-N	CT	White	Soft,Fissured	PLM
16	Main-2F	Office-E	CT	White	Soft,Fissured	PLM
17	Main-2F	Restroom-C	CT	White	Soft,Fissured	PLM
18	Main-2F	Hall-C	CT	White	Soft,Fissured	PLM
19	Main-2F	Landing-C	CT	White	Soft,Fissured	PLM
20	Main	Roof-E	Membrane	Black	Hard,Smooth	PLM
21	Main	Roof-W	Membrane	Black	Hard,Smooth	PLM
22	Main	Roof-N	Membrane	Black	Hard,Smooth	PLM
23	Main-1F	ShipOff-E	CT	White	Soft,Smooth	PLM
24	Main-1F	ShipOff-W	CT	White	Soft,Smooth	PLM

25	Main-1F	Lab-E	Drywall	White	Hard,Smooth	PLM
26	Main-1F	Lab-W	Drywall	White	Hard,Smooth	PLM

SAMPLER: WILLIAM P. RACINE – CAHES #31746
ENVIRONMENTAL CONSULTANT

SIGNATURE:



DATE: November 5, 2012

LAB: ENVIRONMENTAL HAZARDS SERVICES, INC.
7469 WHITE PINE ROAD
RICHMOND VIRGINIA 23237

LAB SIGN.:

DATE: _____
November 6, 2012

BJAAM-SB-Main-COC



Environmental Hazards Services, L.L.C.
 7469 Whitepine Rd
 Richmond, VA 23237
 Telephone: 800.347.4010

Asbestos Bulk Analysis Report

Report Number: 12-11-00611

Client: Environmental Support Network
 5376 Fulton Drive NW
 Canton, OH 44718

Received Date: 11/06/2012
Analyzed Date: 11/07/2012
Reported Date: 11/07/2012

Project/Test Address: BJAAM-SB-Main; Alliance, OH

Client Number:
 36-1963

Fax Number:
 330-494-1650

Laboratory Results

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
12-11-00611-001	01		Gray/White Granular; Silver Paint-Like; Inhomogeneous	Trace <1% Chrysotile	100% Non-Fibrous
Total Asbestos: Trace <1%					
< 1% Chrysotile present in gray granular material.					
12-11-00611-002	02		Gray/White Granular; Silver Paint-Like; Inhomogeneous	Trace <1% Chrysotile	100% Non-Fibrous
Total Asbestos: Trace <1%					
< 1% Chrysotile present in gray granular material.					
12-11-00611-003	03		Gray/White Granular ; Silver Paint-Like; Inhomogeneous	Trace <1% Chrysotile	100% Non-Fibrous
Total Asbestos: Trace <1%					
< 1% Chrysotile present in gray granular material.					
12-11-00611-004	04		Gray/White Granular; Inhomogeneous	Trace <1% Chrysotile	100% Non-Fibrous
Total Asbestos: Trace <1%					
< 1% Chrysotile present in gray granular material.					
12-11-00611-005	05		Gray/White Granular; Inhomogeneous	Trace <1% Chrysotile	100% Non-Fibrous
Total Asbestos: Trace <1%					
< 1% Chrysotile present in gray granular material.					

Environmental Hazards Services, L.L.C

Client Number: 36-1963
Project/Test Address: BJAAM-SB-Main; Alliance, OH

Report Number: 12-11-00611

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
12-11-00611-006	06		Gray/White/Tan Granular; Inhomogeneous	Trace <1% Chrysotile	100% Non-Fibrous
Total Asbestos: Trace <1%					
< 1% Chrysotile present in gray granular material and 2% Chrysotile present in tan granular material.					
12-11-00611-007	07		Gray/White Granular; Inhomogeneous	Trace <1% Chrysotile	100% Non-Fibrous
Total Asbestos: Trace <1%					
< 1% Chrysotile present in gray granular material.					
12-11-00611-008	08		Gray/White Granular; Inhomogeneous	Trace <1% Chrysotile	100% Non-Fibrous
Total Asbestos: Trace <1%					
< 1% Chrysotile present in gray granular material.					
12-11-00611-009	09		White/Gray Granular; Inhomogeneous	Trace <1% Chrysotile	100% Non-Fibrous
Total Asbestos: Trace <1%					
< 1% Chrysotile present in gray granular material.					
12-11-00611-010	10		White/Tan Granular; Inhomogeneous	Trace <1% Chrysotile	100% Non-Fibrous
Total Asbestos: Trace <1%					
Chrysotile present throughout sample.					
12-11-00611-011	11		White/Tan Granular; Inhomogeneous	Trace <1% Chrysotile	100% Non-Fibrous
Total Asbestos: Trace <1%					
2% Chrysotile present in tan granular material.					
12-11-00611-012	12		Gray/White Granular; Inhomogeneous	Trace <1% Chrysotile	100% Non-Fibrous
Total Asbestos: Trace <1%					
<1% Chrysotile present in gray granular material.					
12-11-00611-013A	13	Other *	Brown Fibrous; White Paint Like; Inhomogeneous	NAD	85% Cellulose 15% Non-Fibrous
Fiberboard					

Environmental Hazards Services, L.L.C

Client Number: 36-1963

Report Number: 12-11-00611

Project/Test Address: BJAAM-SB-Main; Alliance, OH

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
12-11-00611-013B	13	Mastic	Tan Adhesive; Homogeneous	NAD	100% Non-Fibrous
12-11-00611-014A	14	Other *	Brown Fibrous; White Paint Like; Inhomogeneous	NAD	85% Cellulose 15% Non-Fibrous
Fiberboard					
12-11-00611-014B	14	Mastic	Tan Adhesive; Homogeneous	NAD	100% Non-Fibrous
12-11-00611-015	15		Yellow Fibrous; White Paint-Like; Inhomogeneous	NAD	85% Fibrous Glass 15% Non-Fibrous
12-11-00611-016	16		Brown Fibrous; White Paint Like; Inhomogeneous	NAD	25% Cellulose 50% Fibrous Glass 25% Non-Fibrous
12-11-00611-017	17		Brown Fibrous; White Paint Like; Inhomogeneous	NAD	25% Cellulose 50% Fibrous Glass 25% Non-Fibrous
12-11-00611-018	18		Brown Fibrous; White Paint Like; Inhomogeneous	NAD	25% Cellulose 50% Fibrous Glass 25% Non-Fibrous

Environmental Hazards Services, L.L.C

Client Number: 36-1963

Report Number: 12-11-00611

Project/Test Address: BJAAM-SB-Main; Alliance, OH

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
12-11-00611-019	19		Brown Fibrous; White Paint Like; Inhomogeneous	NAD	25% Cellulose 50% Fibrous Glass 25% Non-Fibrous
12-11-00611-020	20		Black Tar-Like; Fibrous; Inhomogeneous	NAD	65% Cellulose 35% Non-Fibrous
12-11-00611-021	21		Black Tar-Like; Fibrous; Inhomogeneous	NAD	65% Cellulose 35% Non-Fibrous
12-11-00611-022	22		Black Tar-Like; Fibrous; Inhomogeneous	NAD	65% Cellulose 35% Non-Fibrous
12-11-00611-023	23		Brown Fibrous; White Paint Like; Inhomogeneous	NAD	85% Cellulose 15% Non-Fibrous
12-11-00611-024	24		Brown Fibrous; White Paint Like; Inhomogeneous	NAD	85% Cellulose 15% Non-Fibrous
12-11-00611-025	25		White Chalky; Brown Fibrous; Inhomogeneous	NAD	20% Cellulose 80% Non-Fibrous
12-11-00611-026	26		White Chalky; Brown Fibrous; Inhomogeneous	NAD	26% Cellulose 74% Non-Fibrous

Environmental Hazards Services, L.L.C

Client Number: 36-1963
Project/Test Address: BJAAM-SB-Main; Alliance, OH

Report Number: 12-11-00611

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
-------------------	----------------------	------------	-----------------------	----------	-----------------

QC Sample: 60-NY-35-3829
QC Blank: SRM 1866 Fiberglass
Reporting Limit: 1% Asbestos
Method: EPA Method 600/R-93/116, EPA Method 600/M4-82-020
Analyst: Araceli Enzler



Reviewed By Authorized Signatory:

Tasha Eaddy
QA/QC Clerk

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Each distinct component in an inhomogeneous sample was analyzed separately and reported as a composite. Results represent the analysis of samples submitted by the client. Sample location, description, area, volume, etc., was provided by the client. This report cannot be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report shall not be reproduced except in full, without the written consent of the Environmental Hazards Service, L.L.C. California Certification #2319 NY ELAP #11714. All information concerning sampling location, date, and time can be found on Chain-of-Custody. Environmental Hazards Services, L.L.C. does not perform any sample collection.

Environmental Hazards Services, L.L.C. recommends reanalysis by point count (for more accurate quantification) or Transmission Electron Microscopy (TEM), (for enhanced detection capabilities) for materials regulated by EPA NESHAP (National Emission Standards for Hazardous Air Pollutants) and found to contain less than ten percent (<10%) asbestos by polarized light microscopy (PLM). Both services are available for an additional fee.

400 Point Count Analysis, where noted, performed per EPA Method 600/R-93/116 with a Reporting Limit of 0.25%.

* All California samples analyzed by Polarized Light Microscopy, EPA Method 600/M4-82-020, Dec. 1982.

LEGEND: NAD = no asbestos detected



Analyst Signature Page

Environmental Hazards Services, L.L.C.

7469 Whitepine Rd
Richmond, VA 23237

Telephone: 800.347.4010

Report Number: 12-11-00611

Client: Environmental Support Network
5376 Fulton Drive NW
Canton, OH 44718

Received Date: 11/06/2012

Analyzed Date: 11/07/2012

Reported Date: 11/07/2012

Client Number: 36-1963

Project/Test Address: BJAAM-SB-Main; Alliance, OH

Analyst(s)

A handwritten signature in cursive script that reads "Araceli Enzler".

Araceli Enzler



26 PM

Environmental Support Network, Inc.

5376 Fulton Drive, NW - Canton, Ohio 44718 - (330) 494-0905

CHAIN OF CUSTODY

RUSH

CLIENT: ENVIRONMENTAL SUPPORT NETWORK, INC.
 5376 FULTON DRIVE, NW
 CANTON, OHIO 44718
 PHONE: (330) 494-0905 FAX: (330)-494

A

12-11-00611

SITE: BJAAM-SB-Main
 Alliance, OH



Due Date:
 11/07/2012
 (Wednesday)
 W

ANALYSIS: POLARIZED LIGHT MICROSCOPY
 BULK ASBESTOS ANALYSIS


#	LOCATION	AREA	TYPE	COLOR	TEXTURE	TEST
01	Main -1F	Mill Rm-N	CP	White	Hard,Rough	PLM
02	Main -1F	Mill Rm-S	CP	White	Hard,Rough	PLM
03	Main -1F	Mill Rm-W	CP	White	Hard,Rough	PLM
04	Main -2F	Processing-E	CP	White	Hard,Rough	PLM
05	Main-2F	Processing-W	CP	Green	Hard,Rough	PLM
06	Main-2F	E.Offices-N	CP	Pink	Hard,Rough	PLM
07	Main-2F	E.Stairs-C	CP	White	Hard,Rough	PLM
08	Main-2F	Restroom-C	WP	Orange	Hard,Rough	PLM
09	Main-2F	Processing-N	WP	White	Hard,Rough	PLM
10	Main-1F	E.Stairs-C	WP	Pink	Hard,Rough	PLM
11	Main-2F	E.Stairs-C	WP	Pink	Hard,Rough	PLM
12	Main-2F	OfficeHall-N	WP	White	Hard,Rough	PLM
13	Main-1F	Lab-S	Fume hood	Brown	Soft,Smooth	PLM
14	Main-1F	Lab-N	Fume hood	Brown	Soft,Smooth	PLM
15	Main-1F	Lab-N	CT	White	Soft,Fissured	PLM
16	Main-2F	Office-E	CT	White	Soft,Fissured	PLM
17	Main-2F	Restroom-C	CT	White	Soft,Fissured	PLM
18	Main-2F	Hall-C	CT	White	Soft,Fissured	PLM
19	Main-2F	Landing-C	CT	White	Soft,Fissured	PLM
20	Main	Roof-E	Membrane	Black	Hard,Smooth	PLM
21	Main	Roof-W	Membrane	Black	Hard,Smooth	PLM
22	Main	Roof-N	Membrane	Black	Hard,Smooth	PLM
23	Main-1F	ShipOff-E	CT	White	Soft,Smooth	PLM
24	Main-1F	ShipOff-W	CT	White	Soft,Smooth	PLM

J Stone

11-6-12

25	Main-1F	Lab-E	Drywall	White	Hard,Smooth	PLM
26	Main-1F	Lab-W	Drywall	White	Hard,Smooth	PLM

SAMPLER: WILLIAM P. RACINE - CAHES #31746
ENVIRONMENTAL CONSULTANT

SIGNATURE: 


DATE: November 5, 2012

LAB: ENVIRONMENTAL HAZARDS SERVICES, INC.
7469 WHITE PINE ROAD
RICHMOND VIRGINIA 23237

LAB SIGN.: _____

DATE: November 6, 2012

BJAAM-SB-Main-COC


11-6-12

ATTACHMENT B

BULK ASBESTOS SAMPLING BY POINT-COUNT



POINT COUNT REQUEST FORM

12-11-01115



Environmental Hazards Services, L.L.C.
 7469 Whitepine Rd
 Richmond, VA 23237
 Telephone: 800.347.4010

Due Date:
11/13/2012
 (Tuesday)
 W

Received Date: 11/08/2012
 Client #: 36-1963
 Company Name: Environmental Support Network
 Project/Test Address: BJAAM-SB-Main; Alliance, OH; EHS#12-11-00611
 Analysis Requested: **400 pt Count**

msc

Client Sample #	EHS Sample #	Sample Location and/or Comments
01	12-11-00611-001	Gray Granular material
02	12-11-00611-002	"
03	12-11-00611-003	"
04	12-11-00611-004	"
05	12-11-00611-005	"
06	12-11-00611-006	"
06	12-11-00611-006	Tan Granular material
07	12-11-00611-007	Gray Granular material
08	12-11-00611-008	"
09	12-11-00611-009	"
10	12-11-00611-010	
11	12-11-00611-011	Tan Granular material
12	12-11-00611-012	Gray Granular material

Date Samples Received	Received By	Original Analyst	Date Analyzed	Date Request Received	Received By
11/6/12	Tiffany	Shelly	11/7/12	11/8/12	Michelle



Environmental Hazards Services, L.L.C.
 7469 Whitepine Rd
 Richmond, VA 23237
 Telephone: 800.347.4010

Asbestos 400 Point Count Analysis Report

Report Number: 12-11-01115

Client: Environmental Support Network
 5376 Fulton Drive NW
 Canton, OH 44718

Received Date: 11/06/2012
Analyzed Date: 11/11/2012
Reported Date: 11/13/2012

Project/Test Address: BJAAM-SB-Main; Alliance, OH; EHS#12-11-00611

Client Number:
 36-1963

Fax Number:
 330-494-1650

Laboratory Results

Lab Sample Number	Client Sample Number	Lab Gross Description	% Asbestos	Narrative ID
12-11-01115-001	01 (Basecoat Component Only)	Pale Gray Cementitious	<0.25 % Chrysotile	A12
12-11-01115-002	02 (Basecoat Component Only)	Pale Gray Cementitious	<0.25 % Chrysotile	A12
12-11-01115-003	03 (Basecoat Component Only)	Pale Gray Cementitious	0.25 % Chrysotile	
12-11-01115-004	04 (Basecoat Component Only)	Pale Gray Cementitious	<0.25 % Chrysotile	A12
12-11-01115-005	05 (Basecoat Component Only)	Pale Gray Cementitious	<0.25 % Chrysotile	A12
12-11-01115-006	06 (Basecoat Component Only)	Pale Gray Cementitious	0.25 % Chrysotile	
12-11-01115-007	06 (Surface Coating-Type Component Only)	Beige Brittle	1.25 % Chrysotile	
12-11-01115-008	07 (Basecoat Component Only)	Pale Gray Cementitious	0.25 % Chrysotile	

Environmental Hazards Services, L.L.C

Client Number: 36-1963

Report Number: 12-11-01115

Project/Test Address: BJAAM-SB-Main; Alliance, OH; EHS#
12-11-00611

Lab Sample Number	Client Sample Number	Lab Gross Description	% Asbestos	Narrative ID
12-11-01115-009	08 (Basecoat Component Only)	Pale Gray Cementitious	<0.25 % Chrysotile	A12
12-11-01115-010	09 (Basecoat Component Only)	Pale Gray Cementitious	<0.25 % Chrysotile	A12
12-11-01115-011	10	Off-White to Pale Tan Cementitious	<0.25 % Chrysotile	A12
12-11-01115-012	11 (Basecoat Component Only)	Off-White to Pale Tan Cementitious	0.25 % Chrysotile	
12-11-01115-013	12 (Basecoat Component Only)	Pale Gray Cementitious	<0.25 % Chrysotile	A12

Sample Narratives:

A12: Chrysotile fibers observed but did not fall under any counted points.

Reporting Limit: 0.25 % Asbestos

Method: EPA Method 600/R-93/116, EPA Method 600/M4-82-020

Analyst: Mark Case

Reviewed By Authorized Signatory:



Tasha Eaddy
QA/QC Clerk

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Results represent the analysis of samples submitted by the client. Sample location, description, area, volume, etc., was provided by the client. This report cannot be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report shall not be reproduced except in full, without the written consent of the Environmental Hazards Service, L.L.C. California Certification #2319 NY ELAP #11714.

LEGEND NAD = No Asbestos Detected



Analyst Signature Page

Environmental Hazards Services, L.L.C.

7469 Whitepine Rd
Richmond, VA 23237

Telephone: 800.347.4010

Report Number: 12-11-01115

Client: Environmental Support Network
5376 Fulton Drive NW
Canton, OH 44718

Received Date: 11/08/2012

Analyzed Date: 11/11/2012

Reported Date: 11/13/2012

Client Number: 36-1963

Project/Test Address: BJAAM-SB-Main; Alliance, OH; EHS#12-11-00611

Analyst(s)

A handwritten signature in black ink, appearing to read "Mark Case", written in a cursive style.

Mark Case



Environmental Hazards Services, L.L.C.
 7469 Whitepine Rd
 Richmond, VA 23237
 Telephone: 800.347.4010

Asbestos Bulk Analysis Report

Report Number: 12-11-00811

Client: Environmental Support Network
 5376 Fulton Drive NW
 Canton, OH 44718

Received Date: 11/06/2012
 Analyzed Date: 11/07/2012
 Reported Date: 11/07/2012

Project/Test Address: BJAAM-SB-Main; Alliance, OH

Client Number:
 36-1963

Fax Number:
 330-494-1850

Laboratory Results

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
12-11-00611-001	01		Gray/White Granular; Silver Paint-Like; Inhomogeneous	Trace <1% Chrysotile Total Asbestos: Trace <1%	100% Non-Fibrous
< 1% Chrysotile present in gray granular material.					
12-11-00611-002	02		Gray/White Granular; Silver Paint-Like; Inhomogeneous	Trace <1% Chrysotile Total Asbestos: Trace <1%	100% Non-Fibrous
< 1% Chrysotile present in gray granular material.					
12-11-00611-003	03		Gray/White Granular; Silver Paint-Like; Inhomogeneous	Trace <1% Chrysotile Total Asbestos: Trace <1%	100% Non-Fibrous
< 1% Chrysotile present in gray granular material.					
12-11-00611-004	04		Gray/White Granular; Inhomogeneous	Trace <1% Chrysotile Total Asbestos: Trace <1%	100% Non-Fibrous
< 1% Chrysotile present in gray granular material.					
12-11-00811-005	05		Gray/White Granular; Inhomogeneous	Trace <1% Chrysotile Total Asbestos: Trace <1%	100% Non-Fibrous
< 1% Chrysotile present in gray granular material.					

*Please Paint
 Cont Individual
 Layers
 11/15/12*

Environmental Hazards Services, L.L.C

Client Number: 36-1963

Report Number: 12-11-00611

Project/Test Address: BJAAM-SB-Main; Alliance, OH


Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
12-11-00611-006	06		Gray/White/Tan Granular; Inhomogeneous	Trace <1% Chrysotile	100% Non-Fibrous
Total Asbestos: Trace <1%					
< 1% Chrysotile present in gray granular material and 2% Chrysotile present in tan granular material.					
12-11-00611-007	07		Gray/White Granular; Inhomogeneous	Trace <1% Chrysotile	100% Non-Fibrous
Total Asbestos: Trace <1%					
< 1% Chrysotile present in gray granular material.					
12-11-00611-008	08		Gray/White Granular; Inhomogeneous	Trace <1% Chrysotile	100% Non-Fibrous
Total Asbestos: Trace <1%					
< 1% Chrysotile present in gray granular material.					
12-11-00611-009	09		White/Gray Granular; Inhomogeneous	Trace <1% Chrysotile	100% Non-Fibrous
Total Asbestos: Trace <1%					
< 1% Chrysotile present in gray granular material.					
12-11-00611-010	10		White/Tan Granular; Inhomogeneous	Trace <1% Chrysotile	100% Non-Fibrous
Total Asbestos: Trace <1%					
Chrysotile present throughout sample.					
12-11-00611-011	11		White/Tan Granular; Inhomogeneous	Trace <1% Chrysotile	100% Non-Fibrous
Total Asbestos: Trace <1%					
2% Chrysotile present in tan granular material.					
12-11-00611-012	12		Gray/White Granular; Inhomogeneous	Trace <1% Chrysotile	100% Non-Fibrous
Total Asbestos: Trace <1%					
<1% Chrysotile present in gray granular material.					
12-11-00611-013A	13	Other *	Brown Fibrous; White Paint Like; Inhomogeneous	NAD	85% Cellulose 15% Non-Fibrous

Fiberboard

Please Point Out
 Inhomogeneous Layer


ATTACHMENT C

Site Sketch



- LEGEND**
- = BUILDING
 - = IDENTIFIED AREA
 - = MONITORING WELL
 - = SOIL BORING
 - = TEST PIT
 - = POLE-MOUNTED TRANSFORMER
 - = GAS MAIN
 - = FENCE
 - = RAILROAD TRACKS
 - = PROPERTY LINE



FIGURE 4b:

SAMPLING MAP
112039
FORMER STEWART BROTHERS PAINT
1010 NORTH UNION AVENUE
ALLIANCE, OHIO 44601
FILE NAME= 112039- STEWART-PAINT-
SITE-2-IA-2
DATE: NOVEMBER 9, 2012
APPRX. SCALE: 1"=40'
DRAWN BY: J.P.BREEN

