



# *Environmental Support Network, Inc.*

5376 Fulton Drive, NW – Canton, Ohio 44718 – (330) 494-0905  
www.environmental-support.com

November 14, 2012

Mr. Jay Dahl  
Project Manager  
BJAAM Environmental, Inc.  
P.O. Box 523  
472 Elm Ridge Avenue  
Canal Fulton, Ohio 44614  
(330) 854-5300

RE: The Former Stewart Brothers Paint  
Small Maintenance Storage Shed  
Alliance, Ohio

Dear Jay,

The following includes the results from the asbestos sampling that you requested.

On November 5, 2012, Environmental Support Network, Inc. acquired samples of construction materials from the former Stewart Brothers Paint Property's Small Maintenance Storage Shed located at 1010 North Union Avenue in, Alliance Ohio 44601. The samples were taken of the construction materials resident in the building. Random sampling was conducted pursuant to 40 CFR 763.86. The construction materials sampled are those materials that might become friable during the forces of the planned demolition activity. The purpose of conducting this sampling was to acquire pre-demolition samples of construction materials to satisfy the National Emissions Standards for Hazardous Air Pollutants (NESHAP's) regulations as codified in 40 CFR Part 61.

During this inspection, six-(6) samples were taken. The samples were drywall walls (W), drywall ceiling (C), and building insulation which may become disturbed and friable during the course of the demolition activities. The following chart presents a description of the materials sampled and the associated analytical results.


#	LOCATION	AREA	TYPE	COLOR	TEXTURE	RESULT
01	SmStorage-1F	RestroomW-N	Drywall	White	Hard,Smooth	NAD
02	SmStorage-1F	StorageW-C	Drywall	White	Hard,Smooth	NAD
03	SmStorage-1F	RestroomC-C	Drywall	White	Hard,Smooth	NAD
04	SmStorage-1F	StorageC-C	Drywall	White	Hard,Smooth	NAD
05	SmStorage-1F	Wall-W	Insulation	Brown	Soft,Granular	NAD
06	SmStorage-1F	Attic-C	Insulation	Brown	Soft,Granular	NAD

The aforementioned samples were analyzed utilizing Polarized Light Microscopy (PLM). Sample analysis was conducted pursuant to EPA Method 600/R-93/116. The samples were submitted to an independent testing laboratory known as Environmental Hazards Services in Richmond, Virginia. Environmental Hazards Services is a participant in the National Voluntary Laboratory Accreditation Program (NVLAP).

As can be seen from the above, all of the samples were negative for asbestos content. The NAD designation means, "no asbestos detected" in the sample submitted. These materials need not be removed prior to demolition.

Finally, Jay if you have any questions regarding the above please contact me at (330) 494-0905. As always, thank you.

Sincerely,

A handwritten signature in black ink, appearing to read "William P. Racine" with a stylized flourish at the end.

William P. Racine  
Environmental Consultant  
CAHES #31746

**ATTACHMENT A**

**BULK ASBESTOS SAMPLING BY PLM**



# Environmental Support Network, Inc.

5376 Fulton Drive, NW – Canton, Ohio 44718 – (330) 494-0905

## CHAIN OF CUSTODY

*RUSH*


**CLIENT:** ENVIRONMENTAL SUPPORT NETWORK, INC.  
5376 FULTON DRIVE, NW  
CANTON, OHIO 44718  
PHONE: (330) 494-0905 FAX: (330)-494-1650

**SITE:** BJAAM-SB-SSS  
Alliance, OH

**ANALYSIS:** POLARIZED LIGHT MICROSCOPY  
BULK ASBESTOS ANALYSIS

#	LOCATION	AREA	TYPE	COLOR	TEXTURE	TEST
01	SmStorage-1F	RestroomW-N	Drywall	White	Hard,Smooth	PLM
02	SmStorage-1F	StorageW-C	Drywall	White	Hard,Smooth	PLM
03	SmStorage-1F	RestroomC-C	Drywall	White	Hard,Smooth	PLM
04	SmStorage-1F	StorageC-C	Drywall	White	Hard,Smooth	PLM
05	SmStorage-1F	Wall-W	Insulation	Brown	Soft,Granular	PLM
06	SmStorage-1F	Attic-C	Insulation	Brown	Soft,Granular	PLM

**SAMPLER:** WILLIAM P. RACINE – CAHES #31746  
ENVIRONMENTAL CONSULTANT

**SIGNATURE:**   
**DATE:** November 5, 2012

**LAB:** ENVIRONMENTAL HAZARDS SERVICES, INC.  
7469 WHITE PINE ROAD  
RICHMOND VIRGINIA 23237

**LAB SIGN.:** \_\_\_\_\_  
**DATE:** November 6, 2012

BJAAM-SB-SmStorage-COC



Environmental Hazards Services, L.L.C.  
7469 Whitepine Rd  
Richmond, VA 23237  
Telephone: 800.347.4010

## Asbestos Bulk Analysis Report

Report Number: 12-11-00600

Client: Environmental Support Network  
5376 Fulton Drive NW  
Canton, OH 44718

Received Date: 11/06/2012  
Analyzed Date: 11/07/2012  
Reported Date: 11/07/2012

Project/Test Address: BJAAM-SB-SSS; Alliance, OH

Client Number:  
36-1963

Fax Number:  
330-494-1650

# Laboratory Results

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
12-11-00600-001	01		White Powder; Brown Fibrous; Inhomogeneous	NAD	20% Cellulose 80% Non-Fibrous
12-11-00600-002	02		White Powder; Brown Fibrous; Inhomogeneous	NAD	20% Cellulose 80% Non-Fibrous
12-11-00600-003	03		White Powder; Brown Fibrous; Inhomogeneous	NAD	20% Cellulose 80% Non-Fibrous
12-11-00600-004	04		Brown Powder; Brown Fibrous; Inhomogeneous	NAD	20% Cellulose 80% Non-Fibrous
12-11-00600-005	05		Brown Fibrous; Homogeneous	NAD	88% Cellulose 12% Non-Fibrous

# Environmental Hazards Services, L.L.C

**Client Number:** 36-1963  
**Project/Test Address:** BJAAM-SB-SSS; Alliance, OH

**Report Number:** 12-11-00600

Lab Sample Number	Client Sample Number	Layer Type	Lab Gross Description	Asbestos	Other Materials
12-11-00600-006	06		Brown Fibrous; Homogeneous	NAD	88% Cellulose 12% Non-Fibrous

**QC Sample:** 40-M2-1998-2  
**QC Blank:** SRM 1866 Fiberglass  
**Reporting Limit:** 1% Asbestos  
**Method:** EPA Method 600/R-93/116, EPA Method 600/M4-82-020  
**Analyst:** Christian H. Schaible

Reviewed By Authorized Signatory:



Tasha Eaddy  
QA/QC Clerk

The condition of the samples analyzed was acceptable upon receipt per laboratory protocol unless otherwise noted on this report. Each distinct component in an inhomogeneous sample was analyzed separately and reported as a composite. Results represent the analysis of samples submitted by the client. Sample location, description, area, volume, etc., was provided by the client. This report cannot be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report shall not be reproduced except in full, without the written consent of the Environmental Hazards Service, L.L.C. California Certification #2319 NY ELAP #11714. All information concerning sampling location, date, and time can be found on Chain-of-Custody. Environmental Hazards Services, L.L.C. does not perform any sample collection.

Environmental Hazards Services, L.L.C. recommends reanalysis by point count (for more accurate quantification) or Transmission Electron Microscopy (TEM), (for enhanced detection capabilities) for materials regulated by EPA NESHAP (National Emission Standards for Hazardous Air Pollutants) and found to contain less than ten percent (<10%) asbestos by polarized light microscopy (PLM). Both services are available for an additional fee.

400 Point Count Analysis, where noted, performed per EPA Method 600/R-93/116 with a Reporting Limit of 0.25%.

\* All California samples analyzed by Polarized Light Microscopy, EPA Method 600/M4-82-020, Dec. 1982.

LEGEND: NAD = no asbestos detected



Environmental Hazards Services, L.L.C.  
7469 Whitepine Rd  
Richmond, VA 23237  
Telephone: 800.347.4010

Client: Environmental Support Network  
5376 Fulton Drive NW  
Canton, OH 44718

Client Number: 36-1963

**Project/Test Address:** BJAAM-SB-SSS; Alliance, OH

## Analyst Signature Page

**Report Number:** 12-11-00600

**Received Date:** 11/06/2012

**Analyzed Date:** 11/07/2012

**Reported Date:** 11/07/2012

**Analyst(s)**

---

A handwritten signature in cursive script that reads "Christian H. Schaible".

Christian H. Schaible



6PM

Environmental Support Network, Inc.

5376 Fulton Drive, NW - Canton, Ohio 44718 - (330) 494-0905

CHAIN OF CUSTODY

RUSH

**CLIENT:** ENVIRONMENTAL SUPPORT NETWORK, INC.  
5376 FULTON DRIVE, NW  
CANTON, OHIO 44718  
PHONE: (330) 494-0905 FAX: (330)-494-1

**SITE:** BJAAM-SB-SSS  
Alliance, OH

12-11-00600



**ANALYSIS:** POLARIZED LIGHT MICROSCOPY  
BULK ASBESTOS ANALYSIS

Due Date:  
11/07/2012  
(Wednesday) *WAS*  
W

#	LOCATION	AREA	TYPE	COLOR	TEXTURE	TEST
01	SmStorage-1F	RestroomW-N	Drywall	White	Hard,Smooth	PLM
02	SmStorage-1F	StorageW-C	Drywall	White	Hard,Smooth	PLM
03	SmStorage-1F	RestroomC-C	Drywall	White	Hard,Smooth	PLM
04	SmStorage-1F	StorageC-C	Drywall	White	Hard,Smooth	PLM
05	SmStorage-1F	Wall-W	Insulation	Brown	Soft,Granular	PLM
06	SmStorage-1F	Attic-C	Insulation	Brown	Soft,Granular	PLM

**SAMPLER:** WILLIAM P. RACINE - CAHES #31746  
ENVIRONMENTAL CONSULTANT

**SIGNATURE:** *[Signature]*  
**DATE:** November 5, 2012

**LAB:** ENVIRONMENTAL HAZARDS SERVICES, INC.  
7469 WHITE PINE ROAD  
RICHMOND VIRGINIA 23237


**LAB SIGN.:** *[Signature]* 11-6-12  
**DATE:** November 6, 2012

BJAAM-SB-SmStorage-COC

**ATTACHMENT B**

Site Sketch





Small  
Maintenance  
Storage  
Building

Sewart  
Brothers Paint  
Property